


**PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION
CERTIFICATE**

No. _____


Date: 04.07.2017.


It is certified that an inspection team headed by SRI PRABIN KUMAR BANDOPADHYAY
Sub-Assistant Engineer (RWP), Panch. & Rural Dev. (Name Of Officers with
 designation) from Panchayat & Rural Dev. Para, Dev. Block, Para, (Name of
 Department/Office) inspected the FILIX SCHOOL OF EDUCATION, BARANDANGA,
PARA, PURULIA (Name & Address of
 the School) On 04.07.2017. and found that the FILIX SCHOOL OF EDUCATION,
BARANDANGA, PARA, PURULIA. (Name of school) has safe
 drinking water facilities for the students and members of the institution and is maintaining the hygienic
 sanitation condition in the school building & the campus as per the norms prescribed by the Central/
 State/U.T Govt.


The above valid for a period of two years


Signature with Seal: 
 Name : Prabin Kumar Bandopadhyay
 Designation : Sub-Assistant Engineer,
(RWP), Para-Dev. Block

To _____


PRINCIPAL
 Kendriya Vidyalaya No.-1, HEC
 Ranchi

(Name & Address of the institution)
 Filix School of Education
 an Educational Project of Nanritam

 Manager / Correspondent

FILIX SCHOOL OF EDUCATION

PRINCIPAL


Principal
 Jawahar Navodaya Vidyalaya
 Kalnathar, Bankura (W.B.)